




→ Fortsetzung

M Gießharz-Verbindungs muf fe

Steuer- und Signalkabel											
											
					0,4 mm ²	0,6 mm ²	0,8 mm ²	0,75 mm ²	1,5 mm ²		
Typ	L mm	D mm	H mm	max. Kabel-Ø mm	Anzahl Doppeladern			Anzahl Adern		Art.-Nr.	
M	0	185	32	37	15	6 - 20	6 - 10	6	16	8	124293
	1	240	40	45	22	30 - 70	20 - 30	10 - 20	56	21	124294
	2	265	45	50	30	100 - 150	40 - 70	30 - 40	114	56	124295
	2,5	310	58	65	37	200 - 250	100 - 120	50 - 70	154	96	124296
	3	355	70	80	42	300	150	100 - 120	200	133	124297

Für Fernmeldekabel ist eine Schirmverbindungsleitung SVL erforderlich.